




INSTALLATION ADVICE

PANADERO

1st Case.- Chimney cowl below the ridge line




2nd Case.- Chimney cowl above the ridge, but with nearby high building.

3rd Case.- Chimney cowl fitted to the end.



4th Case.- Obstruction of the smoke outlet pipe.

5th Case.- Obstruction of the pipe due to horizontal overextension (soot acumulation).



PLEASE NOTICE: Smoke has a certain percentage of humidity. When the smoke reaches the flue exit, the temperature difference between the inside and the outside of the pipe causes the condensation of the smoke so it becomes a liquid tar and it can drip from the inside of the pipe wall. This liquid might damage the tile unless the pipe is completely sealed with a refractory mastic.